
CCWD FIELD OPERATIONS

September 2023 Department Report
October 11, 2023



Sandalwood – Forest Meadows



SERVICE LINE REPAIR







SURGE RELIEF REPAIR – INDIAN ROCK ROAD – BIG TREES VILLAGE





SURGE RELIEF REPAIR – INDIAN ROCK ROAD – BIG TREES VILLAGE





USA LINE LOCATING -EBBETTS PASS





RESETTING A BLOW OFF VALVE – EBBETTS PASS






LAKEMONT SERVICE LINE REPAIR – / EBBETTS PASS





WATER QUALITY WORK - EBBETTS PASS






8X6 INCH TRANSITION - LEAK REPAIR





DORRINGTON PRV PIPING – EBBETTS PASS





LOWER ROAD AT WHITE PINES REPAIR





LOWER ROAD AT WHITE PINES REPAIR AND CULVERT INSTALL





WHITE PINES TULE REMOVAL PREP





WHITE PINES TULE REMOVAL PREP






RECONNECTING EXISTING PIPING - LARKSPUR TANK - EBBETTS PASS






PUMPER TRUCK UNIVERSAL JOINT REPLACEMENT






POND 6- FLOATING INTAKE REPAIR - COPPEROPOLIS






KANAFLEX HOSE FLANGE & PIPING REPLACEMENT – 2013 VACCON







NCPA TOUR - NEW SPICER





NCPA TOUR - NEW SPICER







NCPA TOUR - MCKAYS





NCPA TOUR - MCKAYS





NCPA TOUR - ALPINE





GUTTER, CONDUIT, & WIRE INSTALL - FOREST MEADOWS UV





TROUBLESHOOT OF EFFLUENT PUMP 3 - JENNY LIND WTP






IEC STARTER FOR MIXER TROUBLESHOOT – UPPER CC LIFT STATION - COPPEROPOLIS





UPPER CROSS-COUNTRY LIFT STATION PUMP 2 FAIL & HMI FAIL - TROUBLESHOOT



CLEANED MOTOR STARTERS – HUNTERS RESERVOIR PUMP STATION – EBBETTS PASS





WEST POINT WATER AND WASTEWATER SYSTEM TOUR – BLUE MOUNTAIN EMERGENCY PREPAREDNESS COMMITTEE





WEST POINT WATER AND WASTEWATER SYSTEM TOUR – BLUE MOUNTAIN EMERGENCY PREPAREDNESS COMMITTEE



THANK YOU -QUESTIONS

 Director Secada & Members of the Blue Mountain Emergency Preparedness Committee