



CCWD FIELD OPERATIONS

October 2024 Department Report

November 13, 2024



OPERATIONAL DASHBOARD




Service Requests by Category This Year

Last update: 21 minutes ago

- Service Request Totals by Month
- Service Requests By Category This Year**
- Leak Check By Month

OPERATIONAL DASHBOARD




Last update: 22 minutes ago

Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type

OPERATIONAL DASHBOARD



Last update: 23 minutes ago


Work Orders This Year by Crew

Open Work Orders This Month By Crew

Work Orders This Year by Type


OPERATIONAL DASHBOARD

USA Tickets This Year By Group




Last update: 31 minutes ago


OPERATIONAL DASHBOARD




OPERATIONAL DASHBOARD



OPERATIONAL DASHBOARD



OPERATIONAL DASHBOARD




OPERATIONAL DASHBOARD



Last update: 38 minutes ago

Copper Cove Water Production/Consumption

OPERATIONAL DASHBOARD



1-INCH SVC LINE REPAIR – VISTA DEL LAGO – RANCHO CALAVERAS

11/14/2024



SERVICE LINE REPLACEMENT – MILTON ROAD 13

RANCHO CALAVERAS

11/14/2024



SERVICE LINE REPLACEMENT – MILTON ROAD 14

RANCHO CALAVERAS

11/14/2024




SERVICE LINE REPAIR - SIEGEL - RANCHO CALAVERAS

15
1/14/2024



SERVICE LINE REPAIR – MCCAULEY – RANCHO CALAVERAS



TAP SADDLE REPLACEMENT – JENNY LIND RD – RANCHO CALAVERAS



**TAP SADDLE REPLACEMENT – JENNY LIND RD –
RANCHO CALAVERAS**



**TAP SADDLE REPLACEMENT – JENNY LIND RD –
RANCHO CALAVERAS**




BURIED VALVE RECOVERY – RICE COURT – RANCHO CALAVERAS

20
11/14/2024



BURIED VALVE RECOVERY – RICE COURT – RANCHO CALAVERAS

21
11/14/2024



BURIED VALVE RECOVERY – RICE COURT – RANCHO CALAVERAS

11/14/2024



MAIN BREAK REPAIR- HARTVICKSON

23

11/14/2024



MAIN BREAK REPAIR- HARTVICKSON



MAIN BREAK REPAIR- HARTVICKSON



MAIN BREAK REPAIR- HARTVICKSON



MAIN BREAK REPAIR- HARTVICKSON



CANYON RIDGE COURT – EBBETTS PASS

28

11/14/2024



CANYON RIDGE COURT – EBBETTS PASS

29
11/14/2024



CHAPEL OF THE PINES – EBBETTS PASS


30

11/14/2024



CHAPEL OF THE PINES – EBBETTS PASS

31
11/14/2024



NAVAJO DRIVE - EBBETTS PASS

32

11/14/2024



NAVAJO DRIVE - EBBETTS PASS

33

11/14/2024



NAVAJO DRIVE - EBBETTS PASS

11/14/2024



NAVAJO DRIVE - EBBETTS PASS

11/14/2024



NAVAJO DRIVE - EBBETTS PASS



CRYSTAL WAY CORP STOP-EBBETTS PASS



CRYSTAL WAY CORP STOP-EBBETTS PASS



SYSTEM FLUSHING – SHEEP RANCH



ROUTINE WORK – EBBETTS PASS

40

11/14/2024



ROUTINE WORK – EBBETTS PASS

41
11/14/2024



ROUTINE WORK – EBBETTS PASS

42

11/14/2024



2-INCH REPAIR ON WATER LINE – WEST POINT WWTP

13

11/14/2024



ABANDONED TRUCK REMOVAL – WILSON LAKE – WEST POINT

44
11/4/2024



ABANDONED TRUCK REMOVAL – WILSON LAKE – WEST POINT


45
11/4/2024



ABANDONED TRUCK REMOVAL – WILSON LAKE – WEST POINT

46

11/14/2024



ABANDONED TRUCK REMOVAL – WILSON LAKE – WEST POINT

4/
11/4/2024



48

11/14/2024

CONSTRUCTION CREW – TULE REMOVAL – WHITE PINES



49

11/14/2024


CONSTRUCTION CREW – TULE REMOVAL – WHITE PINES



50

11/14/2024

CONSTRUCTION CREW – TULE REMOVAL – WHITE PINES




51

11/14/2024

CONSTRUCTION CREW – TULE REMOVAL – WHITE PINES



ELECTRICAL - ANALYTICAL INSTRUMENT INSTALLATION - WEST POINT WTP



ELECTRICAL-TELEMETRY TROUBLESHOOT 53 DISTRICT WIDE

11/14/2024



ELECTRICAL-TELEMETRY TROUBLESHOOT 54

DISTRICT WIDE

11/14/2024



ELECTRICAL-COPPER COVE WTP EFFLUENT PUMP WIRING FAIL -

55

11/14/2024



THANK YOU – QUESTIONS?