

CCWD FIELD OPERATIONS

April 2023 Department Report

May 24, 2023

Approx 25ft – Crotty - RC



SERVICE LINE REPLACEMENT



SERVICE LINE AND HYDRANT LATERAL REPAIR – CROTTY



SERVICE LINE AND HYDRANT LATERAL REPAIR – CROTTY



2-INCH MAIN BREAK – ABOUAF CT.



2-INCH MAIN BREAK – ABOUAF CT.



2-INCH MAIN BREAK – ABOUAF CT.



SERVICE LINE REPAIR – CLEMENTS PLACE



SERVICE LINE REPAIR – RIPPON



SERVICE LINE REPAIR – RIPPON




8-INCH MAIN – DISSIMILAR METALS - VS



8-INCH MAIN – DISSIMILAR METALS - VS



8-INCH MAIN – DISSIMILAR METALS - VS




FIRE FLOW TESTING – RANCHO CALAVERAS



THUNDERBOLT 2-INCH MAIN – EBBETTS PASS



DARBY RUSSELL 8-INCH MAIN – EBBETTS PASS



DARBY RUSSELL 8-INCH MAIN – EBBETTS PASS



HYDRANT REPAIR MORAN ROAD – EBBETTS PASS



VALVE EXERCISING – EBBETTS PASS



LOCATING DISTRIBUTION SYSTEM FLOW METERS – WEST POINT



LOCATING DISTRIBUTION SYSTEM FLOW METERS – WEST POINT



MOKE RIVER PS CLEAN UP – WEST POINT

22
5/25/2023



MOKE RIVER PS CLEAN UP – WEST POINT

23

5/25/2023



LIFT STATION CLEAN UP – WEST POINT



LIFT STATION CLEAN UP – WEST POINT



BEAR CREEK RAW LINE USA – WEST POINT



VALLECITO WWTP GRIT TANK – VALLECITO



VALLECITO WWTP GRIT TANK – VALLECITO



VALLECITO WWTP GRIT TANK – VALLECITO



VALLECITO WWTP GRIT TANK – VALLECITO



VALLECITO WWTP GRIT TANK – VALLECITO

31

5/25/2023



TRAILER DECK BOARD REPAIR

32

5/25/2023



WALLACE WWTP GENERATOR REPAIR




HUCKLEBERRY LIFT STATION - MUFFIN MONSTER FAILURE




INDIAN ROCK ORENCO POD FILTER CLEANING



CORP YARD – GATE



TROUBLESHOOT & REPAIR OF TELEMETRY RADIO – AZALEA CT. FOREST MEADOWS



TROUBLESHOOT & REPAIR OF TELEMETRY RADIO & PLC - SOUTHWORTH

38

5/25/2023



THANK YOU - QUESTIONS